


BGA Board Hot Air Dryer





Safety valve cuts heater off if air supply is interrupted / insufficient

Heater

BGA Clamping Feature

Safety switch cuts machine off if door is open during operation

Hot air exhaust



AVI PRECISION ENGINEERING PTE LTD

1 KALLANG SECTOR #04-03 SINGAPORE 349276 TEL: 65 67483866 FAX: 65 67484810
E-MAIL: avipre@avipre.com.sg, avipre@avipre.com WEBSITE: www.avipre.com
COMPANY REG NO: 199300584 M SKYPE: avipre