



Conveyors



Use as:

- Linking Conveyor
- Inspection Conveyor
- Buffer Chain Conveyor

Types:

- Twin Flat Belt
- Twin Polycord belt
- Twin Free Flow Chain
- Twin Free Flow Chain with Flat Belt/Polycord

Machine Specifications	
Conveyor Speed	Fixed or Variable
Function Control	PLC
Width Adjustment	Manual Crank
Power Requirements	1 1 0/220VAC 1 Phase-85VA
PCB Transfer Height	920+/-30mm
Machine Color	Standard Beige
Machine Dimensions	L x 550m x PCB Transfer Ht.
Rail Fix/ Flow Directions	To specify
Others	Available On Request

Note: Machine design subject to changes